



DYNAMIC DRAIN
TECHNOLOGIES
 PIPELINING PROFESSIONALS

Defect Score Table Sumner Village Sanitary Lateral Defect Scores

Dynamic Drain Technologies llc.
 2597 Quality Court Unit 114
 Virginia Beach, VA 23454
 757-383-6611

Building	Defect Score	Notes
Community Center	3	Heavy grease deposits with 1 offset and 1 separated joint.
1	3	Heavy cleaning and descaling required in order to assess existing structural defects.
2	3	Heavy grease and scale blocking more than 30% of diameter.
3	4	Very heavy grease deposits and scaling with high potential for underlying structural defects.
4	5	Pipe has suffered material failure with numerous holes and sections missing from the bottom of the pipe. Immediate action required to prevent unexpected interruption of service.
5	5	Pipe has suffered material failure with numerous holes and sections missing from the bottom of the pipe. Immediate action required to prevent unexpected interruption of service.
6	4	Direct lateral - lined. Additional footage of lateral will be taken past first wye.
7	3	Heavy cleaning and descaling required in order to assess existing structural defects.
8	3	Heavy cleaning and descaling required in order to assess existing structural defects.
9	4	Direct lateral - lined. Additional footage of lateral will be taken past first wye.
10	3	Heavy scale evident with heavy cleaning and descaling required to assess underlying structural defects.
11	3	Heavy cleaning and descaling required in order to assess existing structural defects.
12	4	Due to heavy corrosion and grease deposits, survey was abandoned prior to reaching building. Heavy cleaning and descaling required to make full assessment.
13	N/A	Each riser crosses the parking lot and ties directly into the main in front of the building / no access.
14-1	4	Heavy scale and encrustation blocking more than 30% of diameter. Heavy cleaning and descaling required.
14-2	5	Extremely heavy corrosion throughout the bottom of the pipe. Heavy grease blockage over 50%.
14-3	4	Heavy cleaning and descaling required in order to assess existing structural defects.
15-1	3	Heavy cleaning and descaling required in order to assess existing structural defects.
15-2	4	Very heavy grease deposits and corrosion requiring heavy cleaning and descaling to assess existing structural defects.
16-1	4	Heavy cleaning and descaling required in order to assess existing structural defects.
16-2	4	Heavy cleaning and descaling required in order to assess existing structural defects.